

DITCH INSPECTION
EMERGENCY REPAIRS

8-9-00
DATE

Adrianne
COMMISSIONER'S DISTRICT

DITCH # 38

LOCATION (SECTION NUMBER AND LAND OWNER)

Section 22 St. Mary Paul Byron

INSPECTION: Washout on ditch crossing

CORRECTION AND NATURE OF REPAIRS: Clean the washout and fill with crushed rock

COST ESTIMATE: 500⁰⁰ Labor and material

IF COST ESTIMATES WERE RECEIVED FROM A CONTRACTOR: LIST THE NAME OF THE

CONTRACTOR:

SUBMITTED BY: Andy Kajmicki
COUNTY COMMISSIONER OR DITCH INSPECTOR

REMARKS: Lo Ken will do this job

SUBMITTED TO THE COUNTY BOARD ON THE _____ DAY OF _____, 20____.